

5900 Series: QuarterMasters

Available Time Intervals

Number of Pins on CAM	Part #	Motor Speed in RPM			
		1/10 110V AC, 24V AC	1/20 110V AC, 24V AC	1/30 110V AC, 24V AC	1/60 110V AC, 24V AC
2	59-439-2	5	10	15	30
3	59-439-3	3M 20S	6M 40S	10	20
4	59-439-4	2-1/2	5	7-1/2	15
5	59-439-5	2	4	6	12
6	59-439-6	1M 40S	3M 20S	5	10
7	59-439-7	1M 26S	2M 51S	4M 17S	8M 34S
8	59-439-8	1M 15S	2M 30S	3M 45S	7M 30S
9	59-439-9	1M 7S	2M 13S	3M 20S	6M 40S
10	59-439-10	1	2	3	6
12	59-439-12	50S	1M 40S	2M 30S	5

Example:

With a 1/30 RPM Motor and a 5 Pin CAM, the timing per coin deposit is 6 minutes.

GREENWALD INDUSTRIES

212 Middlesex Avenue | Chester, CT 06412 USA | Tel: (860) 526-0800 | Fax: (860) 526-4205
 Toll-Free Tel: 1-800-221-0982 | Toll-Free Fax: 1-800-445-1340
www.greenwaldindustries.com

United States & Canada Customer Service & Technical Assistance:
 Monday–Friday, 8am to 5pm EST.

Contents, specifications and availability are subject to revisions serving the technical improvement.
 Not responsible for any typographical errors.

