


GPAY PLUS

Smart Card Interface Tool v1.1.0.2 Installation and Writing Card Images


1

Go to <https://greenwaldindustries.com/product-literature/> and download the "Smart Card Interface Tool and Instructions (Portable)" to your computer. Extract the files from the "zip" folder




2

Open folder and double click on "SmartcardInterfaceTool.exe" and follow the on screen installation instructions




3

Login using same credentials used to logon to SMS3000




4

- 4a: Choose your Customer name
- 4b: Choose your Account
- 4c: Select "download Image List"



5

- 5a: Choose Image to download from "List of images on Web"
- 5b: Select "Download Selected Image(s)"




6

Insert setup card into Lenovo card reader and plug the USB cable into the computer where SCIT has been installed



7

7a: Select image from "Local (Downloaded) Images"
7b: Select "Write selected image to card"



8

Select "OK"
Remove programmed setup card and use to setup selected machine type

